


Code snippet.


```
SPIM_2_ClearTxBuffer();
SPIM_2_ClearRxBuffer();
CyDelayUs(1u);
SPIM_2_TxEnable(); // also do this in ldriver routine
CyDelayUs(1u);
ldriver (0x020b, 0x0500); // CR2 to pg0, 0-05 W1HL write high order bits land
ldriver (0x022b, 0x0500); // CR2 to pg2, 2-05 W1LL write low order 2bits land don't really need right now


int ldriver (uint16 fword, uint16 sword)
{
    SPIM_2_WriteTxData(fword); // goto pg#
    CyDelayUs(6u); // need 2.7usec min
    SPIM_2_WriteTxData(sword); // set data
    CyDelayUs(6u); // need 2.7usec min
}
```

Correct zeroing of current.




Bad display of zeroing current.





First case first nibble of 1st byte gets swapped with 1st nibble of 2nd byte, both sets.

Second case similar but in second set.



Top trace is SEN, followed by SCLK, then SDAT.

Thursday thought had fixed it by adding clear tx & rx buffer at end of txmt routine.

```
int ldriver (uint16 fword, uint16 sword)


{
    SPIM_2_WriteTxData(fword); // goto pg#
    CyDelayUs(7u); // need 2.7usec min
    SPIM_2_WriteTxData(sword); // set data
    CyDelayUs(7u); // need 2.7usec min
    SPIM_2_ClearTxBuffer(); SPIM_2_ClearRxBuffer();
}
```

Worked fine all morning. Added more routines, then started happening again.


This time the command, instead of 020B, 0500, get 020B, 0200.

No longer swapping, but not updating a nibble.

Below correct.



Then incorrect.



The bidirectional pin is set for resistive pull up.

Name: SPI_M_4

Configure Advanced Built-in

SS
SCLK
MOSI D15 D14 D13 D12 D11 D10 D9 D8 D7 D6 D5 D4 D3 D2 D1 D0
MISO D15 D14 D13 D12 D11 D10 D9 D8 D7 D6 D5 D4 D3 D2 D1 D0
Sample

Mode: CPHA = 1, CPOL = 1
Data Lines: Bidirectional
Data Bits: 16 Shift Direction: MSB First
Bit Rate: 3 Mbps

Name: SPI_M_4

Configure **Advanced** Built-in

Clock Selection:
 Internal Clock External Clock

High Speed Mode:
 Enable High Speed Mode

Buffer Sizes:
Rx Buffer Size (16-bit words): 4
Tx Buffer Size (16-bit words): 4

Interrupts:
 Enable Tx Internal Interrupt Enable Rx Internal Interrupt
 Interrupt On SPI Done Interrupt On Rx FIFO Full
 Interrupt On Tx FIFO Empty Interrupt On Rx FIFO Not Empty
 Interrupt On Tx FIFO Not Full Interrupt On Rx FIFO Overrun
 Interrupt On Byte/Word Transfer Complete
 Interrupt On SPI Idle

Name: PIN_64

Pins Mapping Reset Built-in


Number of Pins: 1

[All Pins] PIN_64_SDAT_1

Type General Input Output


Drive Mode: Resistive Pull Up
Initial State: High (1)

Minimum Supply V_{DD}



As far as rise time of SDAT

With slave connected:



With slave not connected, nothing else on SDAT except a 10k pullup. As below:

The slave datasheet says input currents of 15uA, and when outputs, up to 5mA.

