# CY3271 Pig Tail Thermistor Connector Incorrect

Question: The pig tail connector on the Thermistor does not fit the mating connector on the board.

Response: Remove prongs off thermistor connector with scissors. As polarization is not required for the thermistor, this will not affect the operation of the CY3271 RF Node board. Please refer the attached picture for reference.

If you would like a replacement thermistor with the correct connector please contact Gene Graham at gene@cypress.com.

Remove two prongs with scissors