

Location	Command	Shortcut
File Menu	Open	[Ctrl] + [O]
	Close active file	[Ctrl] + [F4]
	Save	[Ctrl] + [S]
	Save All	[Ctrl] + [Shift] + [s]
	Print	[Ctrl] + [P]
Edit Menu	Undo	[Ctrl] + [Z]
	Redo	[Ctrl] + [Y]
	Cut	[Ctrl] + [X]
	Copy	[Ctrl] + [C]
	Paste	[Ctrl] + [V]
	Delete	[Del]
	Select All	[Ctrl] + [A]
	Find	[Ctrl] + [F]
	Replace	[Ctrl] + [H]
	Batch Find	[Ctrl] + [Shift] + [F]
	Batch Replace	[Ctrl] + [Shift] + [H]
	Go To	[Ctrl] + [G]
	Make Uppercase	[Ctrl] + [Shift] + [U]
	Make Lowercase	[Ctrl] + [U]
	View White Space	[Ctrl] + [E], [S]
	Incremental Search	[Ctrl] + [I]
	Comment Selection	[Ctrl] + [E], [C]
	Uncomment Selection	[Ctrl] + [E], [U]
	Toggle Bookmark	[Ctrl] + [K], [Ctrl] + [K]
	Toggle All Outlining	[Ctrl] + [M], [L]
	Toggle Outlining Expansion	[Ctrl] + [M], [M]
	Start Automatic Outlining	[Ctrl] + [M], [O]
	Stop Automatic Outlining	[Ctrl] + [M], [P]
View Menu	Zoom in	[Ctrl] + [+]
	Zoom out	[Ctrl] + [-]
Sheet / Page	Move item 1 grid unit or Scroll 1 grid unit	[Up], [Down], [Left], or [Right] *
	Move selected shape 1 point	[Shift] + [Up], [Down], [Left], or [Right]
	Move selected shapes off grid **	[Shift] + Left Click (hold) + Drag
	Disable/enable rubber-banding	[Ctrl] + Left Click (hold) on one or more objects + Drag, or [Ctrl] + [Up], [Down], [Left], or [Right]
	Zoom to selection	[Ctrl] + Left Click (hold) on white space + Drag
	Select multiple items	[Ctrl] + Left Click (successive actions)
	Pan	[Alt] + Left Click + Drag
	Scroll up / down	Mouse Wheel Up / Down
	Zoom in / out	[Ctrl] + Mouse Wheel Up / Down
	Scroll left / right	[Shift] + Mouse Wheel Up / Down
	Large scroll up / down	[Page Up] / [Page Down]
	Large scroll left / right	[Shift] + [Page Up] / [Page Down]
Build Menu	Build All Projects	[F6]
	Build Active Project	[Shift] + [F6]
	Cancel Build	[Ctrl] + [Break]
	Compile File	[Ctrl] + [F6]
Code Editor	Auto Complete	[Ctrl] + [Space]
	Find References	[Ctrl] + [Shift] + [R]
	Go To Definition	[F12]
	Go To Implementation	[Ctrl] + [F12]

Location	Command	Shortcut
Debug Menu	Breakpoints	[Ctrl] + [D], [B]
	Output	[Ctrl] + [D], [O]
	Watch 1	[Ctrl] + [D], [W]
	Watch 2	[Ctrl] + [Alt] + [W], [2]
	Watch 3	[Ctrl] + [Alt] + [W], [3]
	Watch 4	[Ctrl] + [Alt] + [W], [4]
	Locals	[Ctrl] + [D], [L]
	Components	[Ctrl] + [D], [P]
	Call Stack	[Ctrl] + [D], [C]
	Memory 1	[Ctrl] + [D], [M]
	Memory 2	[Ctrl] + [Alt] + [M], [2]
	Memory 3	[Ctrl] + [Alt] + [M], [3]
	Memory 4	[Ctrl] + [Alt] + [M], [2]
	Disassembly	[Ctrl] + [D], [D]
	Registers	[Ctrl] + [D], [R]
	Program	[Ctrl] + [F5]
	Execute Code (Debug) / Resume Execution	[F5]
	Debug without Programming	[Alt] + [F5]
	Halt Execution	[Ctrl] + [Alt] + [Break]
	Stop Debugging	[Shift] + [F5]
	Rebuild and Run	[Ctrl] + [Shift] + [F5]
	Reset	[Ctrl] + [Alt] + [F5]
	Step Into	[F11]
	Step Over	[F10]
	Step Out	[Shift] + [F11]
	Toggle Breakpoint	[F9]
	Address Breakpoint	[Ctrl] + [D], [A]
	File Line Breakpoint	[Ctrl] + [D], [F]
	Function Breakpoint	[Ctrl] + [D], [U]
	Variable Watchpoint	[Ctrl] + [D], [V]
	Memory Watchpoint	[Ctrl] + [D], [E]
	Delete all breakpoints	[Ctrl] + [Shift] + F9
Help Menu	Help Topics	[F1]
Design Elements Palette	Cancel current operation	[Esc]
	Rectangle Tool	[R]
	Ellipse Tool	[E]
	Line Tool	[L]
	Text Tool	[T]
	Arc Tool	[C]
	Image Tool	[M]
	Wire Tool	[W]
	Sheet Connector	[S]
	Digital Input	[I]
	Digital Output	[O]
	Digital Inout	[B]
	Analog Terminal	[A]
	External Terminal	[X]
Navigation	Switch between schematic pages.	[Ctrl] + [F6] (Use [Shift] for reverse direction.)
	Switch between open project files.	[Ctrl] + [Tab] (Use [Shift] for reverse direction.)
	<a href="#">Go back to previous cursor location in Code Editor.</a>	[Ctrl] + [-] (Use [Shift] for reverse direction.)